


Understanding G32, G34, G76, and G92 on Fanuc Lathe



CNC Programming Skills: Understanding G32, G34, G76 and G92 on a Fanuc Lathe by S. K. Sinha

★★★★☆ 4.2 out of 5

Language	: English
File size	: 481 KB
Text-to-Speech	: Enabled
Screen Reader	: Supported
Enhanced typesetting	: Enabled
Print length	: 47 pages
Lending	: Enabled



Fanuc lathes are widely used in the manufacturing industry for their precision, reliability, and efficiency. These lathes are controlled by a powerful CNC system that uses G-codes to instruct the lathe on how to perform various operations.

G-codes are a set of standardized commands that are used to control CNC machines. Each G-code has a specific function, such as moving the lathe's axes, controlling the spindle speed, or performing a machining operation.

In this article, we will discuss four commonly used G-codes on Fanuc lathes: G32, G34, G76, and G92. We will explain the function of each G-code, how to use it, and provide examples of how these G-codes can be used in CNC programming.

G32 - Thread Cutting

G32 is used to cut threads on a Fanuc lathe. This G-code can be used to cut a variety of thread types, including:

- Single-start threads
- Multi-start threads
- Tapered threads
- Non-standard threads

To use G32, you must first specify the following parameters:

- The thread type (G32, G33, G34, or G35)
- The thread pitch
- The thread diameter
- The thread length
- The starting point of the thread

Once you have specified the parameters, you can use G32 to cut the thread. The lathe will automatically calculate the correct feed rate and spindle speed based on the specified parameters.

G34 - Thread Tapping

G34 is used to tap threads on a Fanuc lathe. This G-code is similar to G32, but it is specifically designed for tapping threads. Tapping is the process of creating a thread in a pre-drilled hole.

To use G34, you must first specify the following parameters:

- The thread type (G34, G35, G36, or G37)
- The thread pitch
- The thread diameter
- The thread length
- The starting point of the thread

Once you have specified the parameters, you can use G34 to tap the thread. The lathe will automatically calculate the correct feed rate and spindle speed based on the specified parameters.

G76 - Thread Milling

G76 is used to mill threads on a Fanuc lathe. This G-code is similar to G32, but it is specifically designed for milling threads. Milling is the process of creating a thread by cutting a helical groove into a workpiece.

To use G76, you must first specify the following parameters:

- The thread type (G76, G77, G78, or G79)
- The thread pitch
- The thread diameter
- The thread length
- The starting point of the thread

Once you have specified the parameters, you can use G76 to mill the thread. The lathe will automatically calculate the correct feed rate and spindle speed based on the specified parameters.

G92 - Set Workpiece Zero Point

G92 is used to set the workpiece zero point on a Fanuc lathe. This G-code is used to align the workpiece with the lathe's coordinate system.

To use G92, you must first position the workpiece on the lathe's chuck or faceplate. Once the workpiece is positioned, you can use G92 to set the workpiece zero point.


To set the workpiece zero point, you must first move the lathe's axes to the desired zero point. Once the axes are positioned, you can use G92 to set the workpiece zero point.

G32, G34, G76, and G92 are four commonly used G-codes on Fanuc lathes. These G-codes allow you to program and operate your lathe with confidence and efficiency. By understanding the function of each G-code, you can use them to create complex parts and achieve precise results.

If you are new to CNC programming, we recommend that you consult with a qualified machinist or CNC programmer before using these G-codes. These professionals can help you to understand the correct syntax and usage of these G-codes, and they can also provide you with valuable advice on how to use these G-codes to achieve the best results.

CNC Programming Skills: Understanding G32, G34, G76 and G92 on a Fanuc Lathe by S. K. Sinha

★★★★★ 4.2 out of 5




Language : English
File size : 481 KB
Text-to-Speech : Enabled
Screen Reader : Supported
Enhanced typesetting : Enabled
Print length : 47 pages
Lending : Enabled



Letters to My Bipolar Self: A Journey of Hope, Healing, and Acceptance

Bipolar disorder is a serious mental illness that can cause extreme mood swings, from mania to depression. It can be a devastating...



Learning to Breathe from the Breath Itself: A Transformative Guide to Mindfulness and Well-being

In the whirlwind of modern life, finding moments of peace and tranquility can seem like a distant dream. However, within the depths of our own being lies a tool that holds...